


SAFETY CERTIFICATE OF KVS BUILDING/STAFF QUARTER


| | | |
|--|---|--|
| Name of KV | - | Kendriya Vidyalaya AFS, Amla |
| Name / No. of Bldgs | - | 03 Blocks School Building |
| Whether Buildings are safe | - | As per physical verification, no major cracks found in structures. Hence, structures are safe. |
| Major / Minor structural repair Projected by Vidyalaya | - | - |
| Major / Minor structural | - | - |
| Repair are done by Sponsoring agency during Current year | - | - |
| Additional requirements of classrooms / Accommodation are provided by sponsoring agency. | - | - |
| Space of the school / Quarter is Adequate | - | Yes |
| Whether water / Electric supply and Sanitary facilities are provided by sponsoring agency. | - | Yes |

Date :- 13 Apr 18




(Sonal Rajput)
Maj
GE (AF) Amla

COUNTERSIGNATURE


CHAIRMAN
CHAIRMAN
VEC/VMC
KENDRIYA VIDYALAYA
AFS, AMLA

13 APR 18